


Data Sheet for Article: HDCR100269

# IS-1 cable manager brush packed Traverse

1 PU = 2pieces



## SCHRACK-Info

IS-1 cable manager brush traverse

Material: Brush body TPE; brush PE (not yet confirmed)

Brush for covering the cable entry with mounted traverse.

Note: One brush is required for each cable entry.

Comprising:

2 Brush strips

Delivery condition: packed

## Technical Data

|                               |      |
|-------------------------------|------|
| Net weight (kg)               | 0,15 |
| Min. ambient temperature (°C) | -10  |
| Max. ambient temperature (°C) | 60   |

| DESCRIPTION                                               | Order No.  |
|-----------------------------------------------------------|------------|
| IS-1 cable manager brush packed Traverse<br>1PU = 2pieces | HDCR100269 |